

Message Text

LIMITED OFFICIAL USE

PAGE 01 HONG K 00181 070342Z

71

ACTION SY-05

INFO OCT-01 EA-07 ISO-00 AS-01 /014 W

----- 129613

P 070300Z JAN 76

FM AMCONSUL HONG KONG

TO AMEMBASSY CANBERRA PRIORITY

AMEMBASSY JAKARTA PRIORITY

SECSTATE WASHDC PRIORITY 8617

LIMITED OFFICIAL USE HONG KONG 0181

CANBERRA FOR WHITE FROM OIC/RTC

JAKARTA FOR RSO

DEPT FOR SY/EX & SY/T

E.O. 11652: N/A

TAGS: ASEC

SUBJECT: TECHNICAL ASSISTANCE, JAKARTA

REF: (A) HONG KONG 0086 (B) TSR DATED 11/28/75 ON 11/75 JAKARTA

INSPECTION (C) JAKARTA 0112 (NOTAL)

1. CANBERRA WILL NOT POSSESS A COPY OF REF B, WHICH PROVIDES THE SURVEY FOR WORK TO BE PERFORMED IN JAKARTA. PURSUANT TO REF A THE TASKS TO BE PERFORMED IN JAKARTA ARE AS FOLLOWS: INSTALLATION OF THREE CCTV SYSTEMS (ONE OUTDOOR, D/N SYSTEM WITH PAN/TILT CONTROL, ONE INDOOR SYSTEM WITH FIXED LENS AND PAN/TILT SYSTEM, AND ONE INDOOR, FIXED SYSTEM WITH FIXED LENS) WITH MONITORS ON MSG DESK AND RSO'S OFFICE; AND INSTALLATION OF THREE PERIMETER ALARM SYSTEMS WITH MONITOR ON MSG DESK. IN ADDITION, THE RSO HAS REQUESTED THAT TECHNICAL INSPECTIONS AND THE INSTALLATION OF ELECTRICALLY CONTROLLED (BRUTE) LOCKS BE PERFORMED IN MEDAN AND SURABAYA. IF ANY OTHER TASKS HAVE COME UP IN THE INTERIM, REQUEST THAT THE RSO INFORM CANBERRA SOONEST.

2. ALL EQUIPMENT FOR THE CCTV INSTALLATIONS OF REF B WAS PROVIDED BY RTC AND TSO/CANBERRA IN DECEMBER, 1975. CANBERRA HAS PROVIDED TWO CCTV CAMERAS AND THE THIRD, RTC PROVIDED CAMERA,
LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 HONG K 00181 070342Z

WAS SHIPPED TO JAKARTA FROM MANILA (THIS LATTER SYSTEM BEING A D/N

SYSTEM WITH ZOOM LENS AND CONTROL UNIT). RSO HAS REQUESTED AN ADDITIONAL MONITOR POSITION FOR LOBBY COMERA AND RTC WILL SHIP VM201 MONITOR. IN ADDITION THE D/N SYSTEM NOW INSTALLED IN JAKARTA HAS PROVEN INTERMITTANT (POSSIBLY DUE TO DAMAGE TO CAMERA CASE THAT OCCURED IN ORIGINAL SHIPMENT TO JAKARTA); RTC WILL SUPPLY BACKUP D/N SYSTEM (WOULD APPRECIATE HAVING ORIGINAL SYSTEM RETURNED TO RTC IF IT PROVES FAULTY). LOBBY SYSTEM WILL REQUIRE A MODIFIED SWIVEL SO THAT SYSTEM MAY BE OPERATED FROM A PAN/TILT UNIT SUSPENDED FROM THE LOBBY'S CEILING; RTC WILL SHIP SWIVEL FROM MTB-10 TO BE MODIFIED FOR THE PURPOSE.

3. CANBERRA WILL NEED TO SUPPLY THE PERIMETER ALARMS. OMNI-SPECTRA UNITS WOULD PROVIDE BEST SOLUTION AND THREE TRANSMITTER/RECEIVER PAIRS WOULD BE REQUIRED. IF CANBERRA UNABLE TO SUPPLY OMNI-SPECTRA, PROPOSE YOU TRY MORSE IR SYSTEM. RTC UNABLE TO SUPPLY OMNI-SPECTRA AND ALSO UNABLE TO SUPPLY MORSE IR SYSTEM. ONE OF THE PERIMETER RUNS EXCEEDS 500 FEET (BUT NOT MORE THAN 600 FEET), HENCE, REQUEST CANBERRA SUPPLY OG-1000 IR SYSTEM IN CASE MORSE IR SYSTEM UNABLE TO HANDLE DISTANCE IN THIS ONE LOCATION. MSG DESK HAS PDI-803 WITH TWO POSITIONS AVAILABLE. HOWEVER, WOULD RECOMMEND CANBERRA SUPPLY A PDI-801 FOR UTILIZATION WITH PERIMETER ALARMS. IF CANBERRA UNABLE TO SUPPLY PDI-801 AND/OR OG-1000, PLEASE INFORM RTC SOONEST AND RTC WILL SUPPLY.

4. A/SY/EX: TSO WHITE AND BU1 STRINGFIELD WILL REQUIRE TRAVEL AND PER DIEM COVERAGE FOR TRAVEL TO JAKARTA, SURABAYA AND MEDAN WITH A TOTAL TRAVEL TIME OF APPROXIMATELY 16 DAYS.

5. RSO, JAKARTA: REQUEST TABULATION OF CONCORD CCTV CONTROL CABLE (I.E., THE ONE INCH DIAMETER CABLE) NOW ON HAND ACCORDING TO LENGTH. NCOIC/MSG MONITOR WILL REQUIRE ONLY RG-59/U CABLE AS ONLY ONE PAN/TILT CONTROL MECHANISM POSSIBLE. REQUEST YOU UTILIZE BEST JUDGEMENT IN PLACEMENT OF CABLE TO OUTDOOR SYSTEM, REF C, BUT, IF OVERHEAD INSTALLATION PREFERRED WILL NEED ESTIMATE OF TOTAL CABLE RUN DISTANCE.
CROSS

LIMITED OFFICIAL USE

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 JAN 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 07 JAN 1976
Decaption Date: 01 JAN 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Authority: morefirh
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 28 MAY 2004
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1976HONGK00181
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Film Number: D760004-0986
From: HONG KONG
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1976/newtext/t19760180/aaaactjb.tel
Line Count: 98
Locator: TEXT ON-LINE, ON MICROFILM
Office: ACTION SY
Original Classification: LIMITED OFFICIAL USE
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: LIMITED OFFICIAL USE
Previous Handling Restrictions: n/a
Reference: 76 HONG KONG 86
Review Action: RELEASED, APPROVED
Review Authority: morefirh
Review Comment: n/a
Review Content Flags:
Review Date: 20 MAY 2004
Review Event:
Review Exemptions: n/a
Review History: RELEASED <20 MAY 2004 by BoyleJA>; APPROVED <20 MAY 2004 by morefirh>
Review Markings:

Margaret P. Grafeld
Declassified/Released
US Department of State
EO Systematic Review
04 MAY 2006

Review Media Identifier:
Review Referrals: n/a
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
Secure: OPEN
Status: NATIVE
Subject: TECHNICAL ASSISTANCE, JAKARTA
TAGS: ASEC
To: CANBERRA STATE
Type: TE
Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MAY 2006